

BP PLC  
Form 6-K  
April 27, 2010

**SECURITIES AND EXCHANGE COMMISSION**

**Washington, D.C. 20549**

**Form 6-K**

**Report of Foreign Issuer**

**Pursuant to Rule 13a-16 or 15d-16 of  
the Securities Exchange Act of 1934**

for the period ended 26 April 2010

**BP p.l.c.**

(Translation of registrant's name into English)

**1 ST JAMES'S SQUARE, LONDON, SW1Y 4PD, ENGLAND**

(Address of principal executive offices)

Indicate by check mark whether the registrant files or will file annual reports under cover Form 20-F or Form 40-F.

Form 20-F	<input checked="" type="checkbox"/>	Form 40-F
-----		-----

Indicate by check mark whether the registrant by furnishing the information contained in this Form is also thereby furnishing the information to the Commission pursuant to Rule 12g3-2(b) under the Securities Exchange Act of 1934.

Yes

No

IXI

-----

-----

press release  
**April 26, 2010**

**BP GULF OF MEXICO SPILL RESPONSE ACCELERATING**

BP is accelerating offshore oil recovery and continuing well control efforts in Mississippi Canyon Block 252 (MC252) following improvements in weather conditions in the Gulf of Mexico yesterday.

"The safety of the people working offshore is our top priority and the improved weather has created better conditions for our response," said BP Group Chief Executive Tony Hayward. "This, combined with the light, thin oil we are dealing with has further increased our confidence that we can tackle this spill offshore."

BP, operating with the U.S. Coast Guard and other agencies, has launched its comprehensive, pre-approved oil spill response plan following the April 22 sinking of the Transocean Deepwater Horizon drilling rig 130 miles south-east of New Orleans.

According to  
*National Oceanic and Atmospheric Administration*

(  
*NOAA*

) experts participating in the spill response, the spill is "very thin" and consists of "97 per cent sheen."

In Houma, Louisiana where the field operations response is being coordinated, more than 1,000 personnel on and offshore are deployed to coordinate the oil spill response.

BP, as lease operator of MC252, also continues to work below the surface on Transocean's subsea equipment using remotely operated vehicles to monitor the Macondo/MC252 exploration well, and is working to activate the blow-out preventer.

The Transocean drilling rig Development Driller III will arrive on location today to drill the first of two relief wells to permanently secure the well. A second drilling rig, Transocean's Discoverer Enterprise, is en route.

Press enquiries

:

.  
U.S. Coast Guard Joint Information Center 985-902-5231

.  
BP Press Office London +44 20 7496 4076

.  
[www.deepwaterhorizonresponse.com](http://www.deepwaterhorizonresponse.com)

**SIGNATURES**

Pursuant to the requirements of the Securities Exchange Act of 1934, the registrant has duly caused this report to be signed on its behalf by the undersigned, thereunto duly authorized.

BP p.l.c.  
(Registrant)

Dated: 26 April 2010

/s/ D. J. PEARL  
.....  
D. J. PEARL  
Deputy Company Secretary